

GENERAL INDEX

[Illustrated articles are indicated thus.* Editorials are indicated thus†]

A			B		
Abandoned line, salvaging on L. & N.	*66		Ballast and Ballasting:		
Accident:			Cleaning ballast on Pennsylvania	*74	
Chesapeake & Ohio near Paintsville, Ky.	626		Correcting churning in stone ballast	443	
C. St. P. M. & O. near Northline, Wis.	436		Interval between raises when renewing	581	
Denver & Rio Grande Western near			Methods of cleaning	*144	
Echo, Colo.	629		Power ballast cleans cribs	*158	
Erie near Westcolang, Pa.	263		Preventing churning of pit run gravel	333	
Northern Pacific near Big Lake, Wash.	475		Stone or gravel ballast	85	
Air Reduction Sales Company:			Berger Manufacturing Co.	450	
Aircwelding process	*153		Bethlehem Steel Company:		
Airco weld tester	*393		Bethanized wire	*716	
News items	38, 92		News item	98	
Trade publication	232		Bonds, Signal; not used on M-K-T	*382	
American Asphalt Paint Co.	450, 672		Book Review; Ives Tables	393	
American Hoist & Derrick Co.	721		Boston & Maine; switch heaters at North		
American Lumber & Treating Co.	502		station	*205	
American Lumber & Treating Corp.	502		Boxes, stone; see Culverts		
American Museum of Safety; honors sec-			Bridge and Building Supply Men's Associ-		
tion foreman	*381		ation:		
American Railway Bridge and Building			Exhibit at B. & B. convention	659	
Association:			News item	589	
Annual convention	635		Bridges and Bridge Work; see also Con-		
News items 228, 288, 341, 395, 447, 498,	589		crete, Culverts, Paint and Painting,		
American Railway Engineering Associa-			Piles and Pile Driving, Trestles,		
tion:			Welding and Cutting, Fire:		
Convention program	167		Driving rivets with bottled gas	*76	
News items	38, 92		Grouting stone masonry piers	*372	
228, 288, 341, 395, 447, 498, 589, 669,	720		Heartwood in bridge stringers	390	
Report on jacking culverts	*264		Inspecting foundations	165	
Report on effect of weed burners on			Loose Rivets	160	
treated ties	*329		Plans for treated timber bridges	81	
Report on methods of mixing concrete	385		Pointing stone masonry	584	
Report on track grinders	*703		Programming B. & B. work	653	
American Rolling Mill Company	398, 672		Protecting steel floors from corrosion	489	
American Wood-Preservers' Association:			Protecting ties from fire	494	
Convention report	*79		Pulling drift bolts	714	
News items	38, 228, 341, 395, 669,		Purpose of camber	220	
Arc-Welding sets; General Electric Com-	720		Removing overhead bridge	*70	
pany	*157		Replacing floor beams	438	
Armo Culvert Manufacturer's Associa-			Replacing loose rivets	666	
tion	170		Separate or combined gangs?	655	
Armstrong Paint & Varnish Works	170		Tests of stringers	*1418	
Associated Manufacturers' Agencies	170		Treated timber for emergencies	85	
Associations:			Treated timber for bolsters in steel		
Conventions are educational	*1418		spans	580	
Conventions point to better times	1534		Use of guard rails on	657	
Atchison, Topeka & Santa Fe:			Waterproofing deck of Starrucca Valley		
Grooves ties for pins of tie plates	*75		Valley viaduct	*536	
Modernizes water supply facilities	*213				
Statistics on mixture-treated ties	80				
Trestle design revised	*324				
Austin Manufacturing Company	398				
Austin-Western Road Machinery Co.	398				
C			D		
Bucyrus-Erie Company	450, 592		Dams, earth; outlet pipe for	581	
Buhl Sons Company	592		Delaware & Hudson:		
Building and Building Work; see also			Drives rivets with bottled gas	*76	
Concrete, Paint and Painting, Roofs,			Track awards	83	
Terminals, Welding and Cutting:			Denver & Rio Grande Western; derailment		
Alters station to reduce upkeep	*82		near Echo, Colo.	629	
Annual inspections	164		Depression; lessons from the	651	
Finish for wood floors	223		Detroit Graphite Company	170	
Insulation pays	†621		Diesel engines for pumping water	490	
Leakage at drainage opening	*282		Drainage; see also Roadbed:		
Meal worms in dock house	*541		At switches	709	
Must be kept safe	†367		Overcoming slides	*14	
Pier deck of black gum	*209		Reduces maintenance costs	*72	
Platforms repaved under difficulties	*17		Drainage Engineering Company	398	
Separate or combined gangs?	655		Dressing track; see Ballast and Ballasting		
Standardizing hardware	711		Drought; see Water Service		
What material for gutters	493				
Bulkheads, fenders of scrap rail for	*27				
Byers Company, A.M.	292, 398, 502				
E			F		
Canadian National:			Electric Railweld Sales Corp.	344	
Lengthens and strengthens turntables	*480		Embankments; see also Drainage:		
Use of crib walls on	*204		Maintenance of	*547	
Carrie Steel Company:			Repairing slides	160	
I-Beam-Lok armored slab	*586		Employment, influence of work equipment	*139	
News items	98, 450, 592		Erie:		
Cars, Motor:			Accident near Westcolang, Pa.	263	
Fairmont A-37	*285		Pier deck of black gum	*209	
Fairmont Type O engine	*156		Scrap rail fenders	*27	
Improvements to Fairmont 59	*495		Track inspection results	24	
Safety in operation	*273		Track layout made to order	*378	
Caterpillar Tractor Co.	232		Waterproofs deck of Starrucca Valley		
Cement Gun Co.	170		viaduct	*536	
Century Wood Preserving Co., Inc.	170				
Champion Machine & Forging Co.; pipe					
coupling	*157				
Channon Company, H.	398				
Chesapeake & Ohio:					
Air Distribution system for tampers	*479				
Cement-bound Macadam for shop run-					
way	†707				
Derailment near Paintsville, Ky.	626				
Rail-end welding on	*318				
Saws rail with modern equipment	*21				
Track awards	83				
Chicago & North Western:					
Eradicates meal worms in dock house	*541				
Oiling roadbed	*374				
Welding practices at Proviso yard	*429				
Chicago, Burlington & Quincy:					
Alters station to reduce upkeep	*82				
Maintenance work at terminals	*484				
Makes record run with Zephyr	*368				
Repairs 40-year-old viaduct by welding	*432				
Chicago, Rock Island & Pacific:					
Method selecting ties for renewal	†419				
Tests effect of weed burners on creos-					
ote in ties	*329				
Chicago, St. Paul, Minneapolis & Omaha:					
accident near Northline, Wis.	436				
Cleveland Pneumatic Tool Co.	170				
Cleveland Pneumatic Tool Co. of Canada,					
Ltd.	170				
Cleveland Tractor Company:					
Front end loader	*667				
News items	98, 398				
Colorado & Southern; Flood destroys line	*420				
Compressors:					
Gardner-Denver vertical	*225				
Oil engine drive for Ingersoll-Rand	*495				
Concrete:					
Anchoring pipe posts in	336				
Cement-bound Macadam for shop run-					
way	*707				
Central or transit mixed?	385				
High-early-strength in B. & B. work	648				
Making repairs	279				
Corrigan, McKinney Steel Company	721				
Corrosion; protecting bridge floors from	489				
Crane, new Harnischfeger	*285				
Crane Company	42				
Crib Walls:					
Advantages	*204				
When justified?	162				
Crossings, highway:					
Flangeways menace to safety	†65				
Grade separation to relieve unemploy-					
ment	†689				
Massey concrete slab for	*587				
Types of construction	*563				
Crossings, railway; maintenance of	661				
Culverts:					
Economy of various materials for	639				
Jacking methods	*264				
Open joints in pipe culverts	391				
Repairing stone boxes	32				
Curves:					
Computing spirals in string lining	*77				
Rail lubrication on	*271				
Rail wear on	†535				
Transposing rail on	393, 496				
Cyclone Fence Company	170				
D			E		
F			G		
G			H		
H			I		
I			J		
J			K		
K			L		
L			M		
M			N		
N			O		
O			P		
P			Q		
Q			R		
R			S		
S			T		
T			U		
U			V		
V			W		
W			X		
X			Y		
Y			Z		
Z					

International Railway Maintenance Club.....92, 167,	720	Pidgeon-Thomas Iron Co.....	96	S	
International Rail Welding Corp.....	170	Piers; see Bridges and Bridge Work, Build- ings and Building Work		Safety; see also Accidents:	
J		Piles and Pile Driving; see also Trestles		In handling rails and ties.....	*383
Johns-Manville Co.:		Cost of piling.....	221	In handling snow-melting cans and torches.....	87
Transit pipe.....	*154	Jetting piles.....	84	In motor car operation.....	*273
Trade publication.....	292	What kind of hammer line?.....	34	Interesting employees in.....	645
Johns-Manville Sales Corporation.....	42	Pipe:		In using track chisels.....	89
L		Johns-Manville transit.....	*154	New goal in.....	575
LaBour Company, Inc.....	170	What kind of plumbing?.....	585	Sellers Manufacturing Co.....	450
Lehigh Valley:		Pipe Coupling:		Slides; see Drainage, Embankments, Track and Track Work	
Grinding out rail corrugations.....	*172	Champion Machine & Forging Co.....	*157	Snow, see Winter	
Sound roadbed pays way on.....	*260	Hoosier Iron Works.....	*155	Socony-Vacuum Oil Co., Inc.....	672
Letters to the Editor.....	393, *496	Platforms; see also Buildings and Build- ing Work; removing ice from.....	86	Southern Pacific; standard plans for pile trestles.....	*487
Linde Air Products Company:		Plumbing; what kind of pipe for?.....	585	Sperry Rail Service.....	450
C-24 blow pipe.....	*667	Portland Cement Association.....	232	Speeds, high; require good track.....	716
Trade publication.....	398	Power Ballaster Company; power ballaster for crib cleaning.....	*158	Spike, new.....	36
Lining track; see Track and Track Work		Power Tools:		Standard Equipments, Inc.....	344
Long Island; Snow fighting methods.....	*216	Market for.....	*129	Standard Fence Company.....	170
Louisville & Nashville:		Sawing rail with modern equipment.....	*21	Standardization:	
Computing spirals in string lining.....	*77	Take up abandoned line with.....	*66	Is it practical?.....	*621
Retaining wall of scrap rail.....	*28	Type of power for.....	*198	Of rail sections.....	*696
Takes up abandoned line.....	*66	Pumps:		Standard Oil Company of Indiana.....	98
Lubricants; see also curves: Ardeo rail and flange.....	*586	Advantages of triplex.....	714	Stations; see Building and Building Work, Painting	
Lundie Engineering Corporation; Ardeo rail and flange lubricator.....	*586	Electric for water service.....	642	Steel Plate Fabricators' Association.....	170
M		R		Stringers, bridge; tests on.....	*427
McKinney Steel Holding Company.....	721	Rail:		String lining curves; Computing spirals.....	*77
Maintenance Department; see also Organi- zation:		Buying of.....	*328	Sullivan Machinery Company.....	398
Demands on by other departments.....	*470	Can it be standardized?.....	*696	Surfacing Track, see also Tamper:	
Maintenance Equipment Company; Lubri- cator adapted to guard rails.....	*151	Computing tonnage of.....	441	Center-bound track.....	*258
Maintenance of Way; Forecast of expendi- tures.....	*130	Conservation of.....	*561	Interval between raises.....	581
Expenditures and employment increas- ing.....	381, *419	Corrugations a difficult problem.....	*471	Number of jacks.....	489
In busy terminal.....	*484	Lubrication of.....	*472	Switches:	
Recent developments in.....	*627	Modern equipment speeds sawing.....	*21	Drainage at.....	709
Maintenance of Way Club of Chicago.....	720	Orders increase.....	20	Full inspection of.....	*620
Masonry, stone; pointing of.....	584	Orders rise in April.....	267	Gage plates.....	151
Massey Concrete Products Corp.; Concrete highway crossing slab.....	*587	Production in 1933.....	271	Housing switch points.....	90
Mauk, Jerome; wins unique honor.....	*381	P. W. A. loans for.....	371	Syntron Company; New Tie Tamper.....	*332
Metropolitan Track Supervisors' Club.....	720	Safety in handling.....	*383	T	
Missouri-Kansas-Texas; circuits without rail-joint bonds.....	*382	Scrap used in retaining wall.....	*28	Tampers:	
Michigan Central; removes overhead bridge	*70	Transposing on curves.....	165	Air distribution system for.....	*479
Morden Frog & Crossing Works.....	292	Rail, scrap; used in retaining wall.....	*28	New Syntron tie tamper.....	*332
Morrison Metalweld Process, Inc.....	98	Rail Anchors; application of.....	440	Tanks, painting of.....	280
N		Railway & Milan, Inc.....	398	Tanner-Willard Co.....	170
National Lead Company.....	450, 502	Rail Joints; see also Washers, Springs:		Teleweld, Inc.....	344
Nails, roofing.....	*496	Application and care of insulated.....	283	Termites:	
National Lock Washer Company; new spring washer.....	*156	Applying insulated joints.....	330	Enemy of wood.....	*258
National Railway Appliances Association.....	669	Circuits without bonds on M-K-T.....	*382	Methods for combating.....	*269
National Spray Painting and Finishing Association.....	344	Breakage of angle bars.....	*316	Texas Company, The.....	344
New and Improved Devices.....	716	Loosening bolts in.....	653	Tie Plates; see also Rail Laying:	
New York Central:		Oiling fishing surfaces.....	491	Advantages of double shoulder.....	710
Grouting stone masonry piers.....	*372	Selecting for welding.....	488	Advantages of independent fastening.....	159
Platforms removed under difficulties.....	*17	Rail Laying:		Applying lag screws.....	583
Nitrogen, bottled; for riveting.....	*76	Distributing small material.....	582	Grooving ties to receive ribs of.....	*75
Nordberg Manufacturing Co.:		Oiling fishing surfaces.....	491	Independent fastening.....	284
Improves rail and cross grinders.....	*151	Uncoupling released rail.....	218	Tie Plugs; hardwood or softwood?.....	713
New BG rail grinder.....	*444	Where double-shoulder tie plates are used.....	386	Ties:	
Power track wrench improved.....	*157	Which side first.....	34	Dapping bridge.....	716
Norfolk & Western; results of track in- spections.....	24	Rails, Guard; see also Frogs:		Digging in.....	*1198
Northern Pacific:		Incorrect gage.....	33	Effects of weed burners on eroded.....	*329
Derailment at Big Lake, Wash.....	475	Meco lubricator adapted to.....	*151	Fireproofing bridge ties.....	494
Uses steel cap in wood pile trestle.....	*542	Railroad Accessories Corporation; new power bolt tightener.....	*155	Grooved for ribs of tie plates.....	*75
O		Railroad Research Bureau.....	170	How treated ties fail.....	30
Ohio Valley Hardware & Roofing Co.....	398	Railroads:		Inspection of inside tracks.....	660
Oil, Fuel; storage methods.....	163	Aid in emergencies.....	*365	Method of renewing.....	389
Oiling track; see Track and Trackwork		Formulate policies for aggressive ac- tion.....	*619	Number installed in 1932.....	16
Organization:		Future of American.....	546	Method of selecting ties for renewal.....	*424
Affected by use of power tools.....	*621	Government ownership of.....	*315	Renewals demand attention.....	*633
Changes in maintenance of way.....	*630	Important to community.....	*197	Renewing switch ties.....	737
Increased forces present problem in.....	764	Problems of today.....	636	Safety in handling.....	*383
P		Reasons for using.....	*1469	Service records of petroleum treated ties	
Paint and Painting:		Support schools.....	*1257	Spot versus group renewal of.....	80
Brush or spray painting.....	658	Treated unfairly.....	*1417	Time for renewals.....	278
Economy of spray painting.....	327	Rails Company, The:		Use of tools when inspecting.....	679
Effect of zinc chloride treatment on dur- ability of paint.....	81	New Spikes.....	*36	Woolery machine for cutting.....	*152
Painting creosoted lumber.....	653	News item.....	344	Tie Tamper, new syntron	
Painting hot steel surfaces.....	338	Railway Tie Association.....	228, 288	Timken Roller Bearing Co.....	170, 398
Painting interiors.....	21	Railway Track-Work Company; P-21 and P-15 grinders.....	*444	Timken Steel & Tube Company.....	398
Painting radiators.....	440	Reading Iron Company.....	344	Toncan Iron; applied to roof by welding.....	*225
Painting tanks.....	280	Regulation of Transport.....	*127	Track bolts; loosening in cold weather.....	663
Painting zinc chloride treated timber.....	81	Republic Steel Corporation.....	721	Track and Track Work; see also Curves, Drainage, Embankments, Rail Joints, Rail Laying, Roadbed, Rail Anchors, Surfacing Track, Tie Plates, Turn- outs, Welding and Cutting, Winter:	
Pennsylvania:		Reservoirs; see Water Service.....	111	Controlling sliding cuts.....	224
Results of track inspections.....	83	Review of 1933.....	111	Effect of quality of tools on trackwork.....	*141
Roadbed drainage reduces maintenance costs.....	*72	Rivets:		Favorable weather for.....	*1366
Slides cured by drainage.....	*14	Evidence of loose.....	160	Gaging and lining.....	281
Welds corroded rivet heads.....	*539	Replacing loose.....	666	High speeds require good track.....	716
Permanent track construction.....	551	Welding corroded heads.....	*539	Holding track chisels.....	*378
Pettibone-Mulliken Company.....	292	Roadbed, see also Drainage:		Layout made to order.....	711
		Improvements on Lehigh Valley.....	*360	Minimizing heaving.....	*374
		Maintenance of.....	*547	Oiling track on C. & N. W.....	551
		Roadmasters' and Maintenance of Way As- sociation:		Permanent track construction.....	390
		Convention.....	*543	Preparing for lining.....	*368
		News items.....	720	Preparing for Zephyr on C. B. & Q.....	160
		President's address.....	544	Repairing slides.....	*259
		Roofs:		Requirements of higher speeds.....	*66
		Applying corrugated iron by welding.....	*225	Salvaging abandoned line.....	*200
		Material for gutters.....	493	Special track work.....	
		Primer for roofing.....	334	Where to spike when regaging or re- laying rail.....	336
		Replacing slate.....	*387	Track Awards:	
		Wrought iron nails for.....	*496	Chesapeake & Ohio.....	83
		Ross & White Company.....	170, 232	Delaware & Hudson.....	83
		Ruby Railway Equipment Co.....	170	Erie.....	24
		Ryerson, Joseph T. & Son, Inc.....	96	Norfolk & Western.....	24
				Pennsylvania.....	83
				Track Bolts; see also Rail Joints: new	
				Raco tightener.....	*155
				Track Jacks; how many?	489

Track Inspection; see Track Awards		Washers, Spring:		Western Wheeled Scraper Co.	398
Track materials; loans stimulate the buying of.....	*133	National Lock Washer Company.....	*156	Wells:	
Track Supply Association:		Why used.....	25	Gravel wall on I. C.....	*69
List of exhibits at Roadmasters' convention.....	577	Woodings-Verona Triflex spring.....	*152	Concrete-lined on A. T. & S. F.....	*213
News item.....	498	Waterproofing:		Westinghouse Electric & Manufacturing Co.:	
Track Tools:		Causes of failure of.....	715	Flexarc welders mounted on rail cars.....	*152
Improve use of shovels.....	492	Leakage around drainage openings.....	282	Methods for handling welders.....	*482
Misusing adzes.....	220	Starrucca Valley viaduct.....	*536	News items.....	344, 398, 721
Nordberg power wrench.....	*157	Water Service; see also Pipe, Pumps		Trade publications.....	170, 232
Quality in.....	1129	Tanks, Wells:		What's the Answer?.....	29, 84, 159, 218, 278, 333, 386, 437, 488, 579, 660, 709
Should quality govern?.....	*141	Air pockets in suction lines.....	88, 664	Wilson Welder & Metals Co.....	170
Misusing claw bars.....	339	Cleaning silted reservoirs.....	219	Winter:	
Use of track chisel.....	89	Drought a severe test of supplies.....	*316	Ice on platforms.....	86
What tools for tie inspection?.....	579	Effects of dry weather.....	442	Hardest on Bangor & Aroostook.....	*692
Trackwork, special; advancements in.....	*200	Effects of spring floods.....	33	Minimizing heaving track.....	711
Tractor; front end loader for.....	*667	Filtering water.....	391	Snow fighting on the Long Island.....	*216
Transportation, the old deal in.....	638	Hidden waste in pipe lines.....	*317	Switch heaters at North station.....	*205
Treated timbers:		New plant at Topeka.....	*213	Preparing for snow storms.....	*199
Handling of.....	439	Motors or Diesel engines?.....	490	Use of snow plow.....	29
Painting of.....	663	Storage of fuel oil at water stations.....	163	Using torches safely.....	87
Trestles; see also Fire, Piles and Pile Driving:		Supplies menaced by drought.....	323	Wire, Bethanizing process for coating.....	*716
Building Bonnet Carre spillway structures.....	*700	What pipe for plumbing installations.....	585	Wire rope, inspection of in hoisting machines.....	282
Dapping ties on curves.....	716	Water Treatment:		Wonham, Inc.....	170
Design revised by Santa Fe.....	*324	Disposal of sludge.....	334	Woodings Forge & Tool Company.....	450
Improvements in design.....	7534	Progress in.....	*476	Woodings-Verona Tool Works:	
Is greater refinement advisable.....	7317	Weeds:		Triflex spring.....	*152
Maintenance of ballast-deck.....	656	Control of.....	*366	News item.....	450
N. P. has new standard plan.....	*542, 716	Co-ordination of killing equipment.....	338	Wood Preservation:	
Renewing caps.....	665	Fairmont T-29 burner.....	*154	A. W. P. A. holds 30th annual convention.....	*79
S. P. standard plans for.....	*487	Mowing right-of-way.....	388	Handling creosoted material.....	439
Use of work equipment on.....	*128	Welders, car-mounted; methods for handling.....	*482	Plans for treated timber bridges.....	81
Turnouts; using released.....	7535	Welding and Cutting:		Statistics for 1933.....	706
Turntables; lengthen and strengthen on C. N. R.....	*480	Airc welding process.....	*153	Statistics on mixture-treated ties.....	80
Tyson Roller Bearing Corporation.....	721	Airc weld tester.....	*393	Wooley Machine Co.; new tie cutting machine.....	*152
U		At Proviso yard.....	*429	Work Equipment; see also Power Tools:	
Union Pacific; section foreman wins honor.....	*381	Characteristics of arcwelding equipment.....	*275	Condition of.....	*136
United States Steel Corporation.....	42, 170	General electric welding sets.....	*157	Should less be used.....	*139
W		Oxweld Type C-24 blow pipe.....	*667	Worthington Pump & Machinery Corp.....	42
Walls, crib; see Crib Walls		Practices of C. & O.....	*318	X-Y-Z	
Warren Tool Corporation.....	170	Repairing 40-year-old viaduct.....	*433	Yazoo & Mississippi Valley; Bonnet Carre spillway trestle.....	*700
		Repairing special trackwork.....	277	Zephyr makes record run.....	*368
		Selecting joints for welding.....	488		
		Welding corroded rivet heads.....	*539		
		Welding metal roofing.....	*225		
		Westinghouse Flexarc welders.....	*152		
		Welding Equipment & Supply Co.....	96		
		Western-Austin Manufacturing Co.....	398		

PERSONAL MENTION

[Photographs are indicated thus.* Obituaries are indicated thus†]

A			Cruikshank, J. F. 721			Herr, Herbert T. †42		
Adams, E. G., Jr. 230			Czarniecki, M. J. *502			Hicks, A. H. 720		
Adams, E. P. 720				D				
Ades, F. 719				Daem, J. 448		Hoffman, E. L. 96		
Aishton, Richard H. *669				Davis, D., Jr. 719		Holmes, M. V. 230		
Alexander, R. F. 230				Davis, J. 395		Holton, C. R. 98		
Almon, D. J. 98				Dawson, J. B. *670		Honeycutt, J. V. 98		
Anderson, A. C. 342				DeMooy, John 170		Horgan, D. 396		
Anderson, E. F. †232				DeJaiffe, R. 168, 396		Hornsby, L. H. 344		
Anderson, Louis J. †672				DeMoyer, John W., Jr. 290		Hoskins, H. L. 167		
Andrews, H. L. 398				Deutsch, S. 344		Howerton, A. G. 448		
Aquilar, H. C. 38				Diener, R. J. 672		Howland, William I., Jr. *96		
Armstrong, C. E. 167				Dike, Chester T. 500		Hunt, F. S. 230, 290		
Armstrong, Fred. 40				Dilworth, John C. *592		Hunter, H. L. 590		
Asbury, G. P. 500				Ditty, William 342		Hursh, Samuel R. 669, 719		
Ayer, F. C. 396, 448				Doherty, Patrick 290, †292		Huston, R. W. 94		
B				Doughty, M. H. *500		Hutchinson, Joseph B. †168		
Backus, E. W. 344				Drawheim, C. A. 342, 719		Hynes, M. V. 398		
Baker, H. M. 168				Drowley, A. 96				
Baker, J. H. 448				Dyke, R. L. 40				
Ball, E. E. 447					E			
Balusz, Fred C. †448				Edmundson, K. G. T. 96		I		
Barnes, Albert F. 170				Elder, J. D. 590		Irvine, J. A. 40		
Barr, C. A. 342				Elfborg, H. G. 398				
Battis, John H. 396				Ericson, E. G. †672				
Batchelder, W. O. 398				Erickson, W. A. 396				
Beach, H. W. 344				Evans, L. A. 230, 290				
Beatty, L. D. 290					F			
Behan, T. J. 447				Fair, J. M. *719				
Behrman, C. H. 94, 196				Farmer, H. M. 168				
Bennett, E. 500				Farnham, Robert 40				
Benny, W. W. 40				Faulk, F. R. 96				
Bickford, R. P. †232, 290				Ferry, John E. 719				
Binks, H. D. 232				Feucht, P. E. 42				
Binkley, J. S. 40				Filbert, William J. 720				
Birchhead, P. H. 592				Flynn, F. E. 168, 720				
Birkeland, O. 448				Foglegren, C. J. 40				
Bisbing, F. B. 40				Poster, W. L. 344				
Blowers, Blair 40				Fox, M. C. 168, 720				
Boorum, A. W. 170				Fox, P. D. 342				
Bowden, Foster S. 502				Freeman, Francis B. †396				
Bowman, R. F. P. 40				Freeman, H. W. 396				
Boyce, C. W. 448, 672				Fulkerson, T. B. 719				
Bressler, Harry F. 290					G			
Bronson, C. B. 342				Geyer, C. J. 290				
Broome, C. M., Jr. 721				Gibbs, B. T. 292				
Brown, Arthur A. 742				Gilbert, G. H. 502				
Brown, Alexander C. 592				Gillum, J. S. 719				
Brown, Charles W. 395				Gingerich, L. E. 290, 719, 396				
Brown, Ralph A. 292				Goggin, Peter J. 721				
Brown, W. G. 500, †502				Gollehon, R. T. 448				
Bruton, J. P. 396				Golladay, F. E. 96				
Bryan, J. A. 719				Goos, Julius H. 500				
Bryant, A. W. 672				Goodwillie, E. E. 98				
Brydone-Jack, H. D. 447				Gordon, P. M. 721				
Buckley, James 718				Gradolph, W. F. 344				
Buckwalter, T. V. 721				Green, L. W. 720				
Burroughs, Dana 167				Greenawalt, W. P. 170, 398				
Burroughs, F. A. 502				Greenough, A. J. 230				
Buskirk, E. A. 590				Gretzinger, W. C. 168, 290				
C				Grim, J. N. 290				
Caldwell, J. J. 40				Grout, Horace C. *670				
Campbell, John B. *292				Grove, Chas. G. 669				
Card, Joseph B. †450				Gudger, H. H. 167, 230				
Carruthers, V. H. 96				Guild, W. A. 230				
Castro, Lorenzo Perez 590				Gustafson, P. 447				
Caswell, John R. 40					H			
Caulley, Ralph G. 232				Haagen, F. J. 40				
Cavanaugh, William 290				Hager, R. C. 590				
Chandler, John F. 502				Hain, G. M. 342				
Chapman, Harry G. 170				Hammond, L. I. 590				
Chausse, L. V. 396				Hamaker, L. S. *450				
Christian, William A. †168				Hand, G. T. 94				
Church, S. L. 719				Hardin, F. H. 342				
Churchill, Charles S. †168				Harding, L. L., Jr. 232				
Clark, Edward S. 592				Harman, W. C. 40				
Clark, H. H. 40				Harper, W. B. 40				
Clarke, H. R. 342				Harrigan, F. D. †672				
Clements, Mack 344				Harris, A. M. 720				
Colaw, O. D. 502				Harris, G. C. 167				
Colgate, Russell E. 721				Hartman, Fred †448				
Colombo, P. 94				Hawkes, T. J. 230				
Condit, F. M. 170				Hayden, James B. 592				
Conley, V. L. 672				Hayes, Hoyt E. 592				
Cook, C. C. *500				Hayes, R. 342				
Cookingham, Joseph F. †232				Heinze, C. W. 42				
Coolidge, T. B. 290				Henggi, Edward J. 42				
Copeland, F. W. 398				Henggi, George T. *721				
Corey, William Ellis 344				Henry, C. J. 167				
Courtenay, William H. †232					Mc			
Covey, H. S. 170				McAdams, M. B. 290, 342				
Craig, L. B. 502				McAllister, L. B. 592				
Crew, E. O. 719				McCall, H. J. 592				
Crockett, C. B. 672, *721				McCauley, Harry L. 592				
Crosby, Frederick 398				McClain, James B. †292				
Cross, E. T. 398				McClelland, E. S. 344				
				McComb, R. J. 450				
				McConnell, J. N. 168				

McDonald, A.	348	Poulson, H. Ross	42	Sturman, J. T.	590
McGregor, S. S.	40	Price, P. G.	396	Supple, W. D.	719
McKeen, Benjamin	*94	Purdy, S. E.	170	Swartz, H. W.	396, 720
McLean, J. R.	719			Swigart, Edmund K.	†450
McMahon, T.	719			Sykes, Samuel H.	†292
McNaughton, W. K.	719				
McNeill, D. A.	447	Quinn, Patrick J.	396		
				T	
				Tanner, E. E.	290
				Tanner, I. B.	170
				Taylor, Myron C.	42
				Teal, J. E.	342
				Tebbetts, George E.	†*40
				Thomas, J. H.	40
				Thompson, B. T.	*98
				Thompson, F. L.	168
				Thompson, W. B.	344
				Thomson, Douglas A.	719
				Timken, H. H.	398
				Timken, Henry H., Jr.	398
				Tobien, R. D.	500
				Torbert, Richard W.	290
				Townley, Calvert	712
				Triplet, P. W.	342
				Trond	398
				Tullar, C. E.	398
				Tryell, H. E.	500
				Uitta, C. R.	396, 447
				Umstadt, William E.	398
				V	
				Van Arsdalen, C. I.	94
				Vandling, J. E.	720
				Vaughn, G. C.	168, 720
				Vernon, N. D.	168
				Vinnedge, R. R.	672
				Vollans, H.	448
				Vorberg, J. C.	502
				W	
				Wade, L.	40
				Waggener, W. C.	344
				Walden, M. P.	232
				Walker, G. P.	232
				Walker, L. G.	168
				Wallace, J. G.	344
				Warren, J. C.	342
				Washburn, Harold O.	672
				Waygood, W. E.	396
				Wechsneider, H. J.	40
				Welborn, Ed	672
				Wendling, G. C.	290
				Werden, K. A.	168, 290
				West, O. R.	44
				Westcott, Raymond	290
				Wetzel, C. C.	502
				Wheaton, F. L.	†232
				Wheeler, F. S.	40
				Whiesler, A. H.	290, 718
				White, J. C.	718
				Willard, G. T.	170
				Willats, A. M.	590
				Williams, O. E.	500
				Wilson, A. O.	†290
				Wiltse, D. E.	40
				Winn, W. W.	670
				Winstead, John	592
				Wood, B. T.	718
				Woods, A. A.	500
				Woosley, D. E.	40
				Working, Robert J.	721
				Wrenshall, J. C.	590
				Wyles, T. R.	170
				X-Y-Z	
				Young, Arthur H.	170
				Young, J. L.	398
				Young, R. C.	230
				Youngs, H. C.	502
				Zimmerman, H.	342, 718

2
0
9
0
4
9

9
0
3
0
5
9
2
2

3
3
0
3
8
2
3
2
37
34

13
39
19
27
53
39

85
85
46
22

09
53

80
69

583
141
281
89
490
700

712
429
836